



FIELD OBSERVATION #08

Project: Washington City Hall & Police Station

Washington, Iowa

Date: April 16, 2020 Time: 1:00 p.m.

Weather: Overcast

Temperature: 43°

Present: Brent Hinson City of Washington

Kristofer Orth Farnsworth Group, formerly Design Alliance

The purpose of this field observation was to review construction progress made to date.

Exterior:

- 1. Contractors have removed portions of the existing paving and are working on excavating the storm sewer lines west of the existing City Hall.
- 2. Form work and reinforcing steel have been installed in preparation for pouring concrete paving.
- 3. Type "G" aluminum storefront frame & glazing has been installed on the south side of Vestibule [131].
- 4. Type "F" aluminum storefront frames on the west side of Phase I have been installed. The installed frames are divided into (4) panes of glass in lieu of (6) per the construction documents and approved submittal 084313-01. We will verify if this is acceptable with the owner.
- 5. The downspouts which will be installed at City Hall shall not have an opening cut in the front face, openings at the sides and back face are acceptable.
- 6. Contractors have started installation of face brick on the east side of the building. The southeast corner has been topped out and they are preparing to complete the bottom courses.
- 7. The City Staff selected the Light Brown Etch finish for the Petersen Precast Concrete Planters.

Interior:

- 1. City Council [139]:
 - a. Porcelain tile work appears to be complete at the Council Desk.
 - b. Acoustic ceiling grid and tile installation is in progress. Light fixtures and ceiling mounted devices have been installed.
 - c. Aluminum storefront frame and glazing are being stored.
- 2. Men's [136]:
 - a. Porcelain floor and wall tile have been completed.
 - b. Toilet accessories have been installed.

- 3. Lobby [132]:
 - a. Contractors are cleaning the installed porcelain floor tile.
 - b. Porcelain accent wall tile has been installed.
 - c. Storefront frame (131B) has been installed, but glazing has not been installed yet.
 - d. Wood trim for window in south wall has been installed. Glazing has not been installed.
- 4. Corridor [143]:
 - a. Contractors are starting the installation of the LVT.
 - b. Contractors are pulling data cabling above the ceiling.
- 5. Copier / Work Area [134]: Casework installation is in progress.
- 6. Wood doors have been delivered to the site. Phase 1 doors were being moved into the building. The Phase 2 doors are being stored in the storage container at the northeast corner of the site.

Respectfully Submitted,

FARNSWORTH GROUP, INC, formerly Design Alliance, Inc.

Kristofer J. Orth, AIA

KJO:bv

Cc: Brent Hinson, City of Washington (for distribution)
John Bushong, Bushong Construction
Mike Fleming, Bushong Construction
Tyler Luttenegger PE, MODUS

Steve Soupir PE, Fox Engineering

Job Book

Enclosures











































































